

Seller's Disclosure Supplemental Statement 1602 Owens Ave, Three Rivers TX 78071

There is mortar cracking on a few locations between the outside bricking due to apparent slight foundation movement. This has been a condition since we bought the house in 2005 that was sealed then and again recently to help keep out insects. We have not observed any cracking or separation of sheet rock so it seems there is no major movement. It is believed there is only slight movement during periods of prolonged dry weather conditions.